

**From:** [Phillip Winsor](#)  
**To:** [Mueller, Brian](#)  
**Subject:** RE: Falcon Refinery RI/FS  
**Date:** Wednesday, March 27, 2013 8:21:08 PM

---

Brian;  
Out this afternoon with wife's dental surgery. I'll get with you first this tomorrow morning.  
Thanks,

Phillip Winsor, P.E.  
Superfund Section  
Remediation Division  
TCEQ  
Phone # (512)239-1054  
Fax # (512)239-2216  
E-mail - [Phillip.Winsor@tceq.texas.gov](mailto:Phillip.Winsor@tceq.texas.gov)

---

**From:** Mueller, Brian [Mueller.Brian@epa.gov]  
**Sent:** Wednesday, March 27, 2013 1:54 PM  
**To:** Phillip Winsor  
**Subject:** Falcon Refinery RI/FS

Good afternoon Phil

I just wanted to send you a note to let you know that EPA is reviewing the data submitted by Falcon for the original RI. We are looking at it to determine if there is a real need to take all of the samples called for in the FSP. Also when I went to the site in February, I noted that there was what appeared to be sandblasting medium on the road and in the wetlands (AOC3). Are there environmental inspections of the facilities adjacent to the site and if not could we discuss how data from adjacent facilities can be collected?

Thanks

Brian W Mueller RPM  
EPA R6 Superfund  
214 665-7167



9597496